

## Big Hyundai Sedans in Stop Light Recall

Monday, 15 December 2014

---

In the United States, Hyundai are recalling just under 43,000 large sedans with stop lights that may not light up when the driver steps on the brake. The affected cars are 2009-11 model Genesis and 2011 Equus sedans; the defect is being described as potential "circuit failure".



Hyundai have notified the US National Highway Traffic Safety Administration; neither NHTSA nor Hyundai are aware of the defect having caused any crashes as of 9 December.

In the first quarter of 2015 the automaker will start notifying owners of affected cars to have a dealership "replace the circuit" free of charge. It is not known whether the same models built in the same plants and sold in Canada, Mexico, and other countries are being scrutinised the problem.