

Hyundai are recalling some 24,400 2015 Genesis vehicles, because water can leak into the tail lamps.



Such is the degree of electronic integration in the car that the water leak can cause an incorrect readout of the engaged transmission gear on the dashboard, causing drivers to think they're in one gear when they're really in another.

The leak can also cause delayed engagement when the driver shifts from Park to Reverse or Drive. The leaky lamps were made by SL, and installed on vehicles made between 21 February 2014 and 24 January 2015. The taillamps are to be not replaced but repaired by Hyundai dealers starting in the second quarter of this year.

It is not known whether identical cars in Canada will be recalled and repaired.